


CMHC & SCHL  
Helping to house Canadians

11 2450 1



Canada



**MOISTURE PROBLEMS IN  
BUILDINGS: A BIBLIOGRAPHY**

**HUMIDITÉ DANS LES  
CONSTRUCTIONS: UNE  
BIBLIOGRAPHIE**

Prepared at:

Canadian Housing Information Centre  
Canada Mortgage and Housing Corporation  
Ground Floor, Annex  
Montreal Road  
Ottawa, Ontario  
K1A 0P7

Préparé au:

Centre canadien de documentation  
sur l'habitation  
Société canadienne d'hypothèques  
et de logement  
Rez-de-Chaussée, Annex  
Chemin Montréal  
Ottawa, Ontario  
K1A 0P7

Revised/Revisée  
July/juillet 1990



**Moisture Problems in Buildings: A Bibliography**  
**Humidité dans les constructions: Une Bibliographie**

- US1                    Abendroth, Harry R. A Design Guide for Dry Basements in  
HD110                Existing Homes: Final Report. Prepared for U.S. Department  
81D23                of Housing and Urban Development, Office of Policy  
                         Development and Research; prepared by AMAF Industries, Inc.  
                         Washington, D.C.: The Office; Springfield, Va.: NTIS, 1981.
- SW5                    Adamson, Bo ... et al. Energy Conservation, Climatic Control  
BR20                and Moisture in Buildings: Research at the Department of  
86D02                Building Science, Lund Institute of Technology, 1980-1985.  
                         Document; 1986: D2. Stockholm, Sweden: Swedish Council for  
                         Building Research, 1986.
- TH                    Air Infiltration and Ventilation Centre. Airborne Moisture  
7015                Transfer: New Zealand Workshop, Proceedings and  
T36                    Bibliographic Review. Technical Note AIVC; AIC-TN-20-87.  
no. 20                Bracknell, Berkshire: The Centre, 1987.
- Ca2                    Alberta. Energy Conservation Branch. Condensation Concerns.  
AL                    ENR Publication ENR 1/17-no. 9. Rev. ed. Edmonton: Alberta  
M10                    Energy, The Branch, 1987.  
87C51
- TH                    American Hotel and Motel Association. Research Foundation.  
9031                Mildew and Moisture Control: Problem Avoidance in New and  
M54                    Existing Hotels and Motels: A Round Table Discussion,  
1990                Feb. 6, 1990, New Orleans Airport Hilton Hotel, Kenner,  
                         Louisiana. Washington, D.C.: The Association, 1990.
- US1                    Anderson, L.O. and Sherwood, G.E. Condensation Problems in  
D5                    Your House: Prevention and Solution. Washington, D.C.:  
74B373                U.S. Dept. of Agriculture, Forest Service, 1974.
- SW5                    Andersson, Ann-Charlotte. Verification of Calculation Methods  
BR20                for Moisture Transport in Porous Building Materials.  
85D06                Document D6: 1985. Stockholm, Sweden: Swedish Council for  
                         Building Research, 1985.

Cal  
MH65  
87M57  
Appin Associates ... et al. Moisture Source Strength: Measurements in Selected Canadian Cities. Prepared for Project Implementation Division, Policy, Research and Programs Sector, Canada Mortgage and Housing Corporation. Principal consultant: Grant Wichenko. Ottawa: The Division, 1987.

Cal  
MH65  
84F37  
B.E.S.T. Corporation (Balanced Energy Systems Technology Inc.). Field Trials of Test Procedures to Determine Internal Moisture Source Strength. Ottawa: Project Implementation Division, Canada Mortgage and Housing Corporation, 1984.

Bales, Erv and Trechsel, Heinz, eds. Moisture Control in Buildings: Workshop Proceedings, September 25-26, 1984. Sponsored by the Moisture Control in Buildings Research Coordinating Committee. Washington, D.C.: Building Thermal Envelope Coordinating Council, c1985.

Bell, H. Noel. Damp: A Practical Guide to Eliminating Dampness in the Irish Home. Dublin: The Author, 1977.

Cal  
MH110  
85L57  
Benson, G.W. Long-Term Stability of Polyethylene Vapour Barrier Film. Prepared for Research Division, Policy Development and Research Sector, Canada Mortgage and Housing Corporation by Plastecnic; principal consultant: G.W. Benson; project manager, CMHC: A.J. Houston; scientific authority: D.J. Carlsson. Ottawa: Research Division, Policy Development and Research Sector, Canada Mortgage and Housing Corporation, 1985.

US1  
HD110  
81D24  
Booth, Raymond W. A Design Guide for Dry Basements in New Homes: Final Report. Washington, D.C.: U.S. Department of Housing and Urban Development, Office of Policy Development and Research; Springfield, VA.: NTIS, 1981.

Brand, R.G. High-Humidity Buildings in Cold Climates: A Case History. DBR paper no. 934. Ottawa: National Research Council of Canada, Division of Building Research, 1980.

Brundrett, G.W. Criteria for Moisture Control. London, England; Boston: Butterworths, 1990.

- Cal  
MH  
86V21      Buchan, Lawton, Parent Limited. Ventilation Alternatives for Maritime Houses: Final Report. Ottawa: Canada Mortgage and Housing Corporation, 1986.
- TA  
681  
S78  
1958      Building Research Advisory Board. A Study of Effectiveness of Concrete Admixtures in Controlling the Transmission of Moisture Through Slabs-on-Ground. Conducted for the Federal Housing Administration; report edited by William S. Brown. Washington, D.C.: Building Research Institute, 1958.
- Building Science Forum of Australia. New South Wales Division. Waterproofing of Buildings: Seminar: Wednesday, 28th June, 1989, at 4.45 p.m., Masonic Centre, cnr. Gouldburn and Castlereagh Streets. Sydney, Australia: The Division, 1989.
- Cal  
MH  
81M56      Burnett, Eric F.P. Moisture Related Problems in Housing in Newfoundland. Ottawa: Canada Mortgage and Housing Corporation, 1981.
- Cal  
MH  
87C03      CMHC/CHBA Builders' Workshops (1987). CMHC CHBA Builders' Workshop: Speaker's Manual. Ottawa: Canada Mortgage and Housing Corporation, 1987.
- Cal  
MH  
88C04      CMHC/CHBA Task Force on Moisture Problems in Atlantic Canada. CMHC/CHBA Joint Task Force on Moisture Problems in Atlantic Canada Final Report. Ottawa: Canada Mortgage and Housing Corporation: Canadian Home Builders' Association, 1988.
- Cal  
PW22  
88D40      Canada. Public Works Canada. Architectural and Engineering Services. Moisture Content Inspections. Building Performance Evaluation Series; D40. Ottawa: Public Works Canada, 1988.
- Cal  
PW22  
88D40      Canada. Travaux publics Canada. Services d'architecture et de génie. Migration de l'humidité. Série sur l'évaluation du rendement; D40. Ottawa: Travaux publics Canada, 1988.
- Cal  
MH  
80C53      Canada Mortgage and Housing Corporation. Condensation in the Home: Where, Why, and What To Do About It = Nature et causes de la condensation dans la maison et mesures préventives. Ottawa: The Corporation, 1980.

Ca1  
MH  
87M51  
Canada Mortgage and Housing Corporation. Moisture and Air: Problems and Remedies. Ottawa: Canada Mortgage and Housing Corporation; Canadian Home Builders' Association, 1987.

Ca1  
MH  
87M57  
Canada Mortgage and Housing Corporation. Moisture Problems. Builders' Series. Ottawa: CMHC, 1987.

SW5  
BR20  
80D37  
Carlsson, Björn; Elmroth, Arne and Engvall, Per-Ake. Airtightness and Thermal Insulation: Building Design Solutions. Stockholm: Swedish Council for Building Research, 1980.

Castle, Richard William. Damp Walls: The Causes and Methods of Treatment of Dampness in Structures: A Practical Handbook for Those Concerned with the Care and Maintenance of Buildings. 3d ed. London: Technical Press, 1964.

Ca1  
MH  
79S73  
Central Mortgage and Housing Corporation. Study for Developing Policy Guidelines re: Funding of Electrically Heated Homes. Ottawa: CMHC, 1979.

S01  
SI5  
71S20  
Chinnery, D.N.W. Keeping High-Rise Buildings Dry. Special Report; BOU20. Pretoria, South Africa: Council for Scientific and Industrial Research, 1971.

Ciz, J.B. Condensation in Structures: State-of-the Art. Report; no. 84-166-K. Toronto: Ontario Hydro, Research Division, 1984.

Ca2  
ON  
EP80  
81H78  
Ciz, J.B. and Jones, W.R. Humidity Ventilator: Design and Preliminary Performance Evaluation. Toronto: Ontario Hydro, Research Division, 1981.

TH  
9031  
C59  
1986  
Coleman, G.R. Guide to Identification of Dampness in Buildings. Sherborne, Dorset: Remedial Technical Services Ltd., 1986.

TH  
9031  
C6  
1985  
Collombet, Raymond. L'humidité des bâtiments anciens: causes et effets, diagnostic, remèdes. Paris: Editions du Moniteur, c1985.



UK2                    Condensation in Housing: A Report on LA Returns, Survey  
SC                      Results, and Remedial Measures. Edinburgh: Building  
DV15                    Directorate, Scottish Development Dept., c1984.  
84C53

Conference on the Problems of Moisture in Historic Monuments,  
Rome, 1967 = Colloque sur les problèmes que pose l'humidité  
dans les monuments anciens, Roma 11-14, X. 1967. Paris:  
International Council of Monuments and Sites, c1969.

Cal                    Construction Details for Air Tightness: Record of the DBR  
RC54                    Seminar/Workshop, October, November 1977 and January 1978.  
80P03                    Proceedings No. 3 of the Division of Building Research.  
                          Ottawa: National Research Council of Canada, Division of  
                          Building Research, 1980.

Cal                    Construction Principles to Inhibit Moisture Accumulation in  
MH                      Walls of New, Wood-Frame Housing in Atlantic Canada:  
85C56                    Advisory Document. Ottawa: Canada Mortgage and Housing  
                          Corporation; Canadian Home Builders' Association, 1985.

Cook, John Philip. Construction Sealants and Adhesives. New  
York: Wiley-Interscience, 1970.

TH                    Corbett, Robert and Miller, Barbara. Infiltration Control:  
7684                    The Air-Vapor Barrier. Butte, MT: National Center for  
D9C67                    Appropriate Technology, 1984.  
1984

Covington, S.A. and McIntyre, I.S. Moisture Conditions in the  
Walls of Timber Frame Houses: The Effects of Holes in Vapour  
Barriers. Aylesbury, Buckinghamshire: Princes Risborough  
Laboratory, 1986.

Croome, Derek J. and Sherratt, A.F.C., eds. Condensation in  
Buildings. London: Applied Science Publishers, 1972.

Diamant, R.M.E. The Internal Environment of Dwellings.  
London: Hutchinson Educational, 1971.

TH                    Duell, John and Lawson, Fred. Damp Proof Course Detailing.  
9031                    2nd ed. London: Architectural Press, 1983.  
D83  
1983

- SW5 Elmroth, Arne. Well Insulated Airtight Buildings: Design and  
BR20 Construction. Document: D10: 1978. Stockholm: Swedish  
78D10 Council for Building Research, 1978.
- Energy Conservation Contractors Warranty Corporation. Report  
on the User-Friendliness of the Moisture Assessment  
Prescriptive Procedure. Prepared for Scanada Consultants  
Limited and Energy Mines and Resources, Canada. Ottawa:  
Energy, Mines and Resources Canada, c1989.
- Ca2 Enerplan Consultants Ltd. and Allen-Drerup-White Ltd.  
ON Primrose Housing Co-operative Moisture Damage Study.  
HO Prepared for Ontario Ministry of Municipal Affairs and  
85P63 Housing, Technical Services Division, Research and  
Development Section. Toronto: Ontario Ministry of Municipal  
Affairs and Housing, 1985.
- Cal Eyre, D. and Jennings, D. Air-Vapour Barriers: A General  
MS Perspective and Guidelines for Installation. 4th ed.  
83A38 Ottawa: Energy, Mines and Resources Canada, 1983.
- CAL Eyre, D. et Jennings, D. Les membranes d'étanchéité:  
MS aperçu général et guide d'installation. 3e éd. Ottawa:  
82A38F Énergie, Mines et Ressources Canada, 1982.
- TH Fairey, Philip ... et al. Latent and Sensible Load  
9031 Distributions in Conventional and Energy Efficient  
L37 Residences: Final Report. Prepared by Philip Fairey ... et  
1986 al., Florida Solar Energy Center for Gas Research Institute.  
Cape Canaveral: The Center; Springfield, Va.: NTIS, 1986.
- Cal Ferguson, Simek, Clark, Engineers and Architects. Attic  
MH Moisture Control North of 60: Investigation and Comparison  
84A76 of Two Potential Solutions. Prepared for Canada Mortgage and  
Housing Corporation. Ottawa: The Corporation, 1984.
- Forest Products Laboratory (U.S.). Condensation Control in  
Dwelling Construction. By Forest Products Laboratory, Forest  
Service, U.S. Department of Agriculture, in collaboration  
with the Division of Standardized Building Codes and  
Materials, Office of the Administrator, Housing and Home  
Finance Agency. Washington: Housing and Home Finance  
Agency, 1949.

- Cal  
RC69  
85N57
- Forgues, Yvan. The Ventilation of Insulated Roofs. Building Practice Note no. 57. Ottawa: National Research Council Canada, Division of Building Research, 1985.
- Forgues, Yvan. La ventilation des toitures isolée. Note sur la construction; 57F. Ottawa: Conseil national de recherches du Canada, Division des recherches en bâtiment, 1985.
- Cal  
MH65  
87C57
- GE Ground Engineering Ltd. Control of Subsurface Moisture: Report on the Use of Sand-Bentonite Backfill. Prepared for Project Implementation Division, Policy, Research and Programs, Canada Mortgage and Housing Corporation by GE Ground Engineering Ltd.; principal consultant: Paul Kozicki. Ottawa: The Division, 1987.
- TH  
9031  
G38  
1986
- Gaze, A.I. Hygrothermal Tests on Timber Framed Wall Panels with U-values Less Than 0.3 w/m<sup>2</sup> K. Research Report; 86/5. High Wycombe, Buckinghamshire: Timber Research and Development Association, 1986.
- TH  
9031  
G39  
1986
- Gaze, A.I. Permeability of Timber and Timber Based Products. Research Report; 86/6. High Wycombe, Buckinghamshire: Timber Research and Development Association, 1986.
- TH  
9031  
G395  
1986
- Gaze, A.I. and Tuckley, A.J.N. Specification, Testing and Performance of Breather Membranes for Timber Frame Housing. Research Report; 86/7. High Wycombe, Buckinghamshire: Timber Research and Development Association, 1986.
- TH  
9031  
G7  
1974
- Gratwick, Reginald Thomas. Dampness in Buildings. 2d. ed. London: Crosby Lockwood Staples, 1974.
- Great Britain. Interdepartmental Working Party on Condensation and Mould in Buildings. Condensation in Dwellings. London: H.M.S.O., 1970-71.

- Cal  
MH  
88C04f      Groupe de travail de la SCHL et de l'ACCH sur les problèmes relatifs à l'humidité dans les régions de l'Atlantique du Canada. Groupe de travail mixte de la SCHL et de l'ACCH sur les problèmes d'humidité des habitations de la région de l'Atlantique du Canada rapport définitif. Ottawa: Société canadienne d'hypothèques et de logement: Association canadienne des constructeurs d'habitations, 1988.
- Cal  
RC51  
81A34      Handegord, G.O. Air Leakage, Ventilation and Moisture Control in Buildings. Ottawa: National Research Council Canada, Division of Building Research, 1981.
- TH  
9031  
F53      Harrje, D.T. ... et al. Field Measurements of Seasonal Wood Moisture Variations in Residential Attics. S.l.: s.n., 198 .
- Haves, Philip. Solar Regenerated Desiccant Dehumidification: Final Report. Report EDF-064. Austin, Tex.: Texas Energy and Natural Resources Advisory Council, Energy Development Fund, 1982.
- 267  
N19      How to Control Moisture in Homes. New York: National Mineral Wool Association, 1953.
- SW5  
BR20  
75D11      Human Responses to Dry, Humidified, and Intermittently Humidified Air: An Experimental Study in Large Office Buildings. Document; D11:1975. By L.O. Anderson et al. Stockholm: Swedish Building Research, 1976.
- L'humidité dans le bâtiment: séminaire. Organisé avec la collaboration de l'UNESCO par le Collège international des sciences de la construction à Saint-Rémy-lès-Chevreuse (France), du 23 au 25 novembre 1982. Paris: Conseil international de la langue française, c1984.
- Cal  
RC54  
84P07      Humidity, Condensation and Ventilation in Houses: Proceedings of the Building Science Insight '83, October, November and December 1983. Proceedings no. 7. Ottawa: National Research Council Canada, Division of Building Research, 1984.
- Hutcheon, N.B. Fundamental Considerations in the Design of Exterior Walls for Buildings. Technical Report no. 13. Ottawa: Division of Building Research, National Research Council, 1953.

Hyland, Richard W. and Hurley, C. Warren. General Guidelines for the On-Site Calibration of Humidity and Moisture Control Systems in Buildings. Prepared for U.S. Navy. Washington, D.C.: U.S. Dept. of Commerce, National Bureau of Standards: For sale by the Supt. of Docs., U.S.G.P.O., 1983.

Cal  
MH65  
87P65

IBI Group. Prairie Moisture Problems: Crawl Space Investigations in Norway House, Manitoba. Prepared for Project Implementation Division, Policy, Research and Programs Sector, Canada Mortgage and Housing Corporation by the IBI Group; principal consultant: Harold Katzin. Ottawa: The Division, 1987.

International CIB/RILEM Symposium on Moisture Problems in Buildings (2nd: 1974: Rotterdam, Netherlands) Papers presented at the Second International CIB/RILEM Symposium on Moisture Problems in Buildings. Rotterdam: s.n., 1974. 2 volumes.

TH  
9031  
I58  
1985

An Investigation of Condensation Dampness At Darnley and Development of Survey Methods for Condensation Dampness Investigation. A project sponsored by Glasgow District Council in the Department of Architecture and Building Science, University of Strathclyde; project supervisor: Thomas A. Markus. Glasgow: The Department, 1985.

Investigations into Damp-Proof Construction of Walls. New Delhi: National Buildings Organisation and UN Regional Housing Centre, ECAFE, 1970.

Kerr, Dale D. Annotated Bibliography on the Rain Screen Principle. Bibliography no. 45. Ottawa: National Research Council of Canada, Division of Building Research, 1985.

US1  
DE79  
81B31

Knab, Lawrence; Mathey, Robert and Jenkins, David. Laboratory Evaluation of Nondestructive Methods to Measure Moisture in Built-up Roofing Systems. NBS Building Science Series; 131. Prepared for Directorate of Engineering and Services, U.S. Air Force. Washington: U.S. Dept. of Commerce, National Bureau of Standards, 1981.

Cal  
RC69  
85N52

Latta, J.K. The Principles and Dilemmas of Designing Durable House Envelopes for the North. Building Practice Note; no. 52. Ottawa: Division of Building Research, National Research Council of Canada, 1985.

- Ca1 Latta, J.K. Principes et problèmes relatifs à la conception  
RC69 d'enveloppes de bâtiment durables dans le Nord Canadien.  
85N52f Note d'information sur la construction, no. 52F. Ottawa:  
Division des recherches en bâtiment, Conseil national de  
recherches Canada, 1985.
- Ca2 Lee, Tang G. Condensation in Manufactured Housing. Prepared  
AL for Alberta Municipal Affairs, Housing Division, Research and  
MA65 Development Section. Edmonton: Alberta Municipal Affairs,  
87C55 1987.
- TH Lieff, M. and Trechsel, H.R., eds. Moisture Migration in  
9031 Buildings: A Symposium. Sponsored by ASTM Committee E-6 on  
M64 Performance of Building Constructions, Philadelphia, Pa., 6  
1982 Oct. 1980. Philadelphia, Pa. (1916 Race St., Philadelphia  
19103): ASTM, c1982.
- TH Louvigné, Michel et Peccard, Jean-Paul. Prévention et  
9031 traitement de l'humidité: techniques et produits. Memento  
L68 CATED; 38. Paris: Centre d'assistance technique et de  
1985 documentation: Institut technique du bâtiment et des travaux  
publics, 1985.
- Marsh, Paul. Air and Rain Penetration of Buildings.  
Lancaster; New York: Construction Press, 1977.
- TH Marsh, Paul. Thermal Insulation and Condensation. Lancaster,  
9031 Eng.: Construction Press, 1979.  
M275
- Marshall, Terry. Atlantic Canada Wood Framing Moisture  
Survey. Ottawa: Canada Mortgage and Housing Corporation,  
1990.
- Ca1 Marshall Macklin Monaghan Limited. Moisture Induced Problems  
MH110 in NHA Housing. Prepared for the Research Division, Policy  
83M53 Development and Research Sector of Canada Mortgage and  
Housing Corporation by Marshall Macklin Monaghan Limited;  
principal consultants, J.H. VanPoorten, J. Timusk, J.  
Melchers; CMHC Project Manager, Alvin J. Houston. Ottawa:  
Canada Mortgage and Housing Corporation, c1983. 3 vols.

- TH  
9031  
T4  
Marshall Macklin Monaghan Limited. Testing and Evaluation of Dehumidification Equipment in NHA Housing: Newfoundland. S.l.: Marshall, Macklin, Monaghan, 1983.
- TH  
9031  
C66  
1988  
Merrill, John and Parrott, Kathleen, eds. Condensation and Related Moisture Problems in the Home. Urbana-Champaign: American Association of Housing Educators and Small Homes Council-Building Research Council, University of Illinois at Urbana-Champaign, c1988.
- TH  
9031  
M47  
Merrill, John L. Moisture Problems in the Home. Madison, Wis.: University of Wisconsin-Extension, Cooperative Extension Service, 1986?
- Cal  
MT259  
82R01  
Middleton Associates. Energy Conservation and House Basements: A Research Report. Prepared by Middleton Associates, under a sub-contract from the Saskatchewan Research Council. BETT Publication 82.01. Ottawa: Energy, Mines and Resources Canada, 1982.
- Cal  
PW25  
79T35  
Mill, Peter A. Thermography: A New Building Science Tool. Ottawa: Public Works Canada, Design and Construction (Technology) Branch; Built Works Directorate, Architecture Division, 1979.
- Moisture Control. Don Mills, Ont.: Canadian Consulting Engineer, 1979.
- TH  
9031  
M62  
1986  
Moisture in Houses: Control Technology for Designers and Builders. Energy Design Update. Arlington, Mass.: Cutter Information Corporation, c1986.
- TH  
9031  
M65  
1985  
Moisture Problems in Residential Construction: Separating Myth from Reality. Sponsored by Washington Energy Extension Service, Oregon State University, Extension Energy Program and Puget Sound Power and Light. Seattle: Washington Energy Extension Service, 1985.
- Cal  
MH110  
87D61  
Morrison Hershfield Limited. Drying Characteristics in Outer Walls of Low Rise Residential Housing: Final Report. Prepared for the Research Division, Policy Development and Research Sector, Canada Mortgage and Housing Corporation. Ottawa: The Division, 1987.

Mould Growth in Buildings: Proceedings of a joint BRE/Paint Research Association seminar held at the Building Research Establishment Princes Risborough Laboratory on 11 and 12 June 1980. Princes Risborough, England: Princes Risborough Laboratory, 1981.

TH  
9031  
B3  
1978

NAHB Research Foundation. Basement Water Leakage ... Causes, Prevention, and Correction. Rev. ed. Washington: National Association of Home Builders, c1978.

TH  
9031  
P54  
1966

NAHB Research Foundation. A Pilot Study of the Causes, Prevention and Correction of Basement Water Leakage Problems for National Association of Home Builders. Rockville, Md.: The Foundation, 1966.

National Association of Home Builders. Controlling Moisture in Homes. Washington: NAHB, 1987.

US1  
EM  
83M53

National Center for Appropriate Technology. Moisture and Home Energy Conservation: How to Detect, Solve and Avoid Related Problems. Prepared for U.S. Department of Energy, Assistant Secretary, Conservation and Renewable Energy, Small Scale Technology Branch, Appropriate Technology Program. Washington, D.C.: United States Department of Energy, 1983.

Newman, A.J. Rain Penetration Through Masonry Walls: Diagnosis and Remedial Measures. Report BR 117. Garston, Watford: Building Research Establishment, 1988.

TH  
9031  
N57  
1989

Nisson, J.D. Ned. Moisture Control for Homes: A Primer for Designers and Builders. Energy Design Update. Arlington, Mass.: Cutter Information Corporation, c1989.

Cal  
MH65  
88W55

Oboe Engineering. Wood Moisture Monitoring, Halifax, Nova Scotia: Final Report. Ottawa: Canada Mortgage and Housing Corporation, Project Implementation Division, 1988.

Cal  
MH65  
88W56

Oboe Engineering. Wood Siding Moisture Monitoring, St. John's, Newfoundland: Final Report. Ottawa: Canada Mortgage and Housing Corporation, Project Implementation Division, 1988.



TH Oliver, Alan C. Dampness in Buildings. New York: Nichols  
9031 Publications, c1988.  
045  
1988

Cal Onysko, D.M. and Jones, S.K. Development of Vapour  
MH110 Permeability Data for Waferboard. Prepared for the Research  
88D28 Division, Policy Development and Research Sector, Canada  
Mortgage and Housing Corporation by Forintek Canada  
Corporation. Ottawa: Canada Mortgage and Housing  
Corporation, 1988.

TH Orr, Harold. Report Regarding Moisture in Floor Space.  
9031 Saskatoon: Harold Orr and Associates, 1987.  
077  
1987

TH Oxley, T.A. and Gobert E.G. Dampness in Buildings: Diagnosis,  
9031 Treatment, Instruments. London; Boston: Butterworths, 1983.  
094  
1983

SW5 Pettersson, Bertil and Axen; Bengt. Thermography: Testing of  
BR20 the Thermal Insulation and Airtightness of Buildings.  
80D05 Document D5: 1980. Stockholm: Swedish Council for Building  
Research, 1980.

Cal Pine, Michael. Problems with Attic Moisture: A Review of  
MH Corrective Measures Taken to Eliminate Snow Infiltration and  
82P68 Hoar-Frost Accumulation in the Attics of Northern Homes.  
Ottawa: Canada Mortgage and Housing Corporation, 1982.

Cal Platts, R.E. Field Survey of Moisture-Troubled Walls in  
MH110 Newfoundland Houses. Prepared for the Technical Research  
81F37 Division of Canada Mortgage and Housing Corporation by  
Scanada Consultants Limited. Ottawa: CMHC, 1981.

- TH  
9031  
P56  
1983
- Platts, R.E. Wet Walls in Canadian Houses: Problems, Solutions, Policy. Ottawa: Scanada Consultants Limited, 1983.
- Powell, Frank J. and Robinson, Henry E. The Effect of Moisture on the Heat Transfer Performance of Insulated Flat-Roof Constructions. NBS Building Science Series, no. 37. Washington: U.S. National Bureau of Standards; for sale by the Supt. of Docs., U.S. Govt. Print. Off., 1971.
- Cal  
MH  
85C56
- Principes de construction visant à prévenir l'accumulation d'humidité dans les murs des nouvelles maisons à ossature de bois des régions de l'Atlantique du Canada: conseils et recommandations. Ottawa: Société canadienne d'hypothèques et de logement; Association canadienne des constructeurs d'habitations, 1985.
- Quantities, Symbols and Units for the Description of Heat and Moisture Transfer in Building: Conversion Factors. Publication no. 37. Rotterdam: CIB, c1977.
- Cal  
RC69  
85N54
- Quirouette, R.L. The Difference Between a Vapour Barrier and an Air Barrier. Building Practice Note; no. 54. Ottawa: National Research Council Canada, Division of Building Research, 1985.
- Cal  
RC69  
85N54F
- Quirouette, R.L. La différence entre un pare-vapeur et un pare-air. Note sur la construction; BPN; 54F. Ottawa: Conseil national de recherches Canada, Institut de recherche en construction, c1985.
- RILEM/CIB Symposium on Moisture Problems in Buildings (1965: Helsinki, Finland) Moisture Problems in Buildings: RILEM/CIB Symposium 1965. Helsinki: s.n., 1965.
- TH  
7684  
D9R6  
1984
- Roussel, Michel. Aération des logements. Paris: Editions Eyrolles, c1984.

- Cal  
MH110  
88D61      Rowan Williams Davies and Irwin Inc. Drying Characteristics in Timber Frame Walls of Low-Rise Residential Housing: Final Report. Submitted to the Research Division, Policy Development and Research Sector, Canada Mortgage and Housing Corporation. Ottawa: The Corporation, 1988.
- US1  
D  
70M11      Rule, Richard Henry. Making Basements Dry. Home and Garden Bulletin no. 115. Rev. Washington: U.S. Dept. of Agriculture; for sale by the Supt. of Docs., U.S. Govt. Print. Off., 1970.
- Cal  
MH  
87C03F      SCHL/ACCH ateliers des constructeurs (1987) SCHL/ACCH ateliers des constructeurs: guide de l'animateur. Ottawa: Société canadienne d'hypothèques et de logement, 1987.
- UK1  
EN90  
82D15      Sanders, C.H. and Cornish, J.P. Dampness: One Week's Complaints in Five Local Authorities in England and Wales. London: Building Research Establishment: H.M.S.O., 1982.
- Cal  
MH  
84C53      Sawers, John W. Condensation in the Home: Where, Why, and What to do About It. Rev ed. Ottawa: Canada Mortgage and Housing Corporation, 1984.
- Cal  
MH  
84C53      Sawers, John W. Nature et causes de la condensation dans la maison et mesures préventives. Nouvelle révision. Ottawa: Société canadienne d'hypothèques et de logement, 1984.
- Scanada Consultants. Avoiding Moisture Problems when Retrofitting Canadian Houses to Conserve Energy: Executive Summary for Report. By Scanada Consultants Limited with A.T. Hansen and Provincial Consultants Limited, SAR Engineering, Marshall Macklin Monaghan Limited. Ottawa: Energy Mines and Resources Canada, 1988, c1989.
- Cal  
MH110  
85C55      Scanada Consultants. Computer Model of the Drying of the Exterior Portion of Wood-Frame Walls: Updated Version. Prepared by Scanada Consultants Limited for Morrison Hershfield Limited. Ottawa: Canada Mortgage and Housing Corporation, 1986.

Cal  
MH110  
80F34  
Scanada Consultants. Field Investigations of Moisture Related Problems in Nova Scotia. Report for the Technical Research Division of Canada Mortgage and Housing Corporation. Ottawa: CMHC, 1980.

Cal  
MH110  
80F33  
Scanada Consultants. Field Investigations of Moisture Related Problems in Prince Edward Island. Prepared for the Technical Research Division of Canada Mortgage and Housing Corporation by Scanada Consultants. Ottawa: CMHC, 1980.

Scanada Consultants. The MAPP, a Moisture Assessment and Prescriptive Procedure: Chapter 5 of the Report Avoiding Moisture Problems when Retrofitting Canadian Houses to Conserve Energy; report for Energy, Mines and Resources Canada by Scanada Consultants Limited with A.T. Hansen and Provincial Consultants Limited, SAR Engineering, Marshall Macklin Monaghan Limited. Ottawa: Energy, Mines and Resources Canada, 1988, c1989.

TH  
9031  
S28  
Scanada Consultants. A Survey of Moisture Problems in the Thermally Upgraded Existing Houses: Report. Prepared by Scanada Consultants Limited; for the Division of Building Research of the National Research Council. Ottawa: Scanada Consultants Limited, 1979.

Cal  
RC69  
84N49  
Scott, D.L. Field Visits to Moisture Troubled Housing in a Maritime Climate. Building Practice Note; no. 49. Ottawa: Division of Building Research, National Research Council Canada, 1984.

Cal  
RC64  
83N05  
Scott, D.L. Seasonal Moisture Variation in Wood Siding and Framing: A Case Study. Building Research Note; no. 205. Ottawa: Division of Building Research, National Research Council Canada, 1983.

Seiffert, Karl. Damp Diffusion and Buildings: Prevention of Damp Diffusion Damage in Buildings Design. Transl. from the German by A.B. Phillips and F.H. Turner. Amsterdam; New York: Elsevier Pub. Co., 1970.

Cal  
MH110  
87P27

Sheltair Scientific Limited. The Performance of Sealed and Insulated Venting Systems in Combination with High Pressure Oil Burners. Prepared for Research Division, Canada Mortgage and Housing Corporation; study prepared by Sheltair Scientific Limited, Scanada-Sheltair Consortium Incorporated; principal consultant: Sebastian Moffatt. Ottawa: The Division, 1987.

Simmons, H. Leslie. Repairing and Extending Weather Barriers. New York: Van Nostrand Reinhold, c1989.

Smith, Baird M. Dampness in Historic Buildings: Methods of Diagnosis and Treatment: Preliminary Report. Washington, D.C.: U.S. Dept. of the Interior, Heritage Conservation and Recreation Service, Technical Preservation Services Division, 1980.

Smith, Baird M. Moisture Problems in Historic Masonry Walls: Diagnosis and Treatment. Washington, D.C.: U.S. Dept. of the Interior, National Park Service, Preservation Assistance Division: For sale by the Supt. of Docs., U.S.G.P.O., 1984.

Cal  
MH  
87M51F

Société canadienne d'hypothèques et de logement. L'Air et l'humidité: problèmes et solutions. Ottawa: Société d'hypothèques et de logement; Association canadienne des constructeurs d'habitations, 1987.

Cal  
MH  
80C53

Société canadienne d'hypothèques et de logement. Natures et causes de la condensation dans la maison et mesures préventives = Condensation in the Home: Where, Why, and What to do About It. Ottawa: La Société, 1980.

Cal  
MH  
88M57F

Société canadienne d'hypothèques et de logement. Les problèmes d'humidité. 2ième édition. Ottawa: La Société, 1987.

TH  
9031  
S63  
1983

Speidel, Karl. Diffusion et condensation de vapeur d'eau dans le bâtiment: processus physique calcul d'après une nouvelle méthode graphique. Traduit et adapté de l'allemand par Jean-Louis Cauchepin. Paris: PYC édition, 1983.

Strelka, C.S. Indoor Swimming Pools: Humidity Caused Problems and Suggested Solutions. ISRC Facility Subcommittee and National Research Council, Institute for Research in Construction. Toronto: Ontario Ministry of Tourism and Recreation, 1987.

Ca2  
SA  
RS  
85M56

Sulatisky, M.T. Moisture Problems at the Borealis Housing Cooperative. Submitted to the Energy Conservation Division, Department of Public Works and Highways, Government of the N.W.T. SRC Publication no. R-823-2-E-85. Saskatoon: Saskatchewan Research Council, 1985.

Symposium: Moisture-Proofing of Buildings: Proceedings. Pretoria: Council for Scientific and Industrial Research, National Building Research Institute, 1971. 2 volumes.

Symposium on Air Infiltration, Ventilation and Moisture Transfer (1986: Fort Worth, Texas) Symposium on Air Infiltration, Ventilation and Moisture Transfer: Worthington Hotel, Fort Worth, Texas, December 2-4, 1986. Symposium chairman, David Eakin. Washington, D.C.: Building Thermal Envelope Coordinating Council, 1986.

Symposium on Humidity Applications - Commercial, Industrial and Residential (1972: New Orleans, La.). Papers presented at the Symposium on Humidity Applications - Commercial, Industrial and Residential: at the semiannual meeting of the American Society of Heating, Refrigerating and Air-Conditioning Engineers, January 23-27, 1972, New Orleans, Louisiana. New York, NY: American Society of Heating, Refrigerating and Air-Conditioning Engineers, c1973.

Symposium on Humidity Measurement (1968: Columbus, Ohio). Papers presented at the Symposium on Humidity Measurement: at the semiannual meeting of the American Society of Heating, Refrigerating and Air-Conditioning Engineers, February 5-8, 1968, Columbus, Ohio. New York, NY: American Society of Heating, Refrigerating and Air-Conditioning Engineers, c1970.

TH  
2235  
S95  
1967

Symposium on Weathertight Joints for Walls (1967: Oslo, Norway) Weathertight Joints for Walls = Les joints muraux étanches aux intemperies. CIB report; 11. Oslo: Norwegian Building Research Institute, 1968.

- Cal  
MH305  
80R28
- TES Limited. A Review of Ventilation Requirements for Residential Buildings in Canada. Prepared for Canada Mortgage and Housing Corporation, Technical Research Division. TES Report No; C289-1. Ottawa: CMHC, 1980.
- TH  
1101  
C354  
SP3  
1980
- Thermal Insulation. CWC Datafile SP-3. Ottawa: Canadian Wood Council, 1980.
- Ref.  
Z  
7144  
C76C66  
1984
- Timber Research and Development Association. Condensation. TRADA Library Bibliography TLB 129. Hughenden Valley, England: TRADA, 1984.
- UK1  
EN92  
78P16
- Thorogood, R.P. and Rodwell, D.F.G. Moisture in the Walls of Timber-framed Dwellings. Building Research Establishment Current Paper; CP16/78. Buckinghamshire, Eng.: Building Research Establishment, Dept. of the Environment; Springfield, Va.: National Technical Information Service, 1978.
- Trechsel, Heinz R. and Bomberg, Mark, eds. Water Vapor Transmission Through Building Materials and Systems: Mechanisms and Measurement. ASTM Special Technical Publication; no. 1039. Philadelphia, PA: ASTM, c1989.
- Cal  
MH65  
87B11
- Unies Limited. Basement Condensation: Field Study of New Homes in Winnipeg. Prepared for Project Implementation Division, Policy, Research and Programs, Canada Mortgage and Housing Corporation by Unies Limited; principal consultant, Cam MacInnes. Ottawa: The Division, 1987.
- Cal  
MH65  
87B12
- Unies Limited. Basement Condensation: Field Study of New Homes in Winnipeg: Summary Report. Prepared for Project Implementation Division, Policy, Research and Programs, Canada Mortgage and Housing Corporation by Unies Limited; principal consultant, Cam MacInnes. Ottawa: The Division, 1987.

TH Van Straaten, J.F. Thermal Performance of Buildings. Elsevier  
7225 Architectural Science Series. Amsterdam; New York:  
V35 Elsevier, Pub. Co., 1967.

Ref. Vance, Mary. Dampness in Buildings: A Bibliography.  
Z Architecture Series: Bibliography; A-500. Monticello, Ill.:  
5941 Vance Bibliographies, 1981.  
V3  
no. 500

Ref. Vance, Mary. Dampness in Buildings: A Revision of A 500.  
Z Architecture Series: Bibliography; A-1591. Monticello,  
5941 Ill.: Vance Bibliographies, 1986.  
V3  
no. 1591

US1 Verrall, Arthur F. and Amburgey, Terry L. Prevention and  
HD Control of Decay in Homes. Washington: Department of  
79P61 Housing and Urban Development, 1979.

Voluntary Test Method for Condensation Resistance of Windows,  
Doors and Glazed Wall Sections. Chicago, Ill.:  
Architectural Aluminum Manufacturers Association, 1981.

TH Water Penetration in Buildings: A Research Study and  
9031 Recommendations for Solution. [S.l.: s.n., 197?].  
W37

Weather Proofing: Seminar, Wednesday, July 16, 1986 at  
4:45 p.m., Masonic Centre, Castlereagh Street, Sydney.  
Sydney: Building Science Forum of Australia, New South Wales  
Division, 1986.

Weatherproofing Existing Buildings: Seminar: Wednesday,  
April 17, 1985 at 4:45 p.m., Masonic Centre, Castlereagh  
Street, Sydney. Sydney: Building Science Forum of  
Australia, New South Wales Division, 1985.

White, Jim H. Moisture Transport in Walls: Canadian  
Experience. Authorized reprint from Standard Technical  
Publication 1039. Philadelphia, P.A.: American Society for  
Testing and Materials, 1989.



- Cal  
MH110  
84S76
- White, Jim H. A Summary of Questions Asked at NRC's Building Science Insight '83: "Humidity, Condensation and Ventilation in Houses". Prepared by J.H. White of Canada Mortgage and Housing Corporation, Research Division, as a service to the National Research Council of Canada, Division of Building Research. Ottawa: Canada Mortgage and Housing Corporation, 1984.
- CAL  
MH  
84V23
- White, Jim H. Ventilation for Humidity Control: A Research Report. Ottawa: Canada Mortgage and Housing Corp., 1984.
- TH  
9031  
W48  
1983
- Whiting, D. Assessment of Potential Techniques for In-situ, Real Time Moisture Measurements in Building Envelope Systems - A Literature Survey: Report. Prepared by Construction Technology Laboratories ... for Building Thermal Envelope Systems and Materials, Oak Ridge National Laboratory. Skokie, Ill.: Construction Technology Laboratories: available from the National Technical Information Service, U.S. Department of Commerce, 1983?
- US1  
DE70  
40R63
- Woolley, Harold W. Moisture Condensation in Building Walls. Washington, D.C.: U.S. Dept. of Commerce, National Bureau of Standards, 1940; Springfield, Va.: National Technical Information Service, 1973.

